



Karnataka Fire and Emergency Services Department
Office of the District fire officer,
Tumkur Fire station
BH Road, Tumkur - 572 103.
Ph No.0816 - 2283101.



Date:10-08-2026.

No.214/CC/DFO/TFS/2026.

To,
The Authorized Signatory
M/s. Elite International. School,
NS Road, Kadaba,
Gubbi Taluk,
Tumkur District.

Sub : Issue of "Compliance report" with respect to fire prevention, fighting and evacuation measures maintained at **M/s. Elite International. School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.**

Ref : Fire Safety Recommendation C.No.214/FSR/DFO/TFS/2026. Dt:-10/08/2026


*** **

With reference to subject above cited, 'Fire Safety Recommendation' was issued wide reference (1) to the premises of **M/s. Elite International. School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.** with a condition to fulfill the recommendations and compliance the same within 3 months.

The applicant has requested to this office for Issue of Compliance Certificate. In this regard I have inspected the premises on 10-08-2026 for issuing Compliance Certificate. the management **M/s. Elite International. School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.** Was complied the all recommendation communicated in Fire Safety Recommendation except training part.

Under the above circumstances the Karnataka Fire & Emergency Services Department is issuing the 'Fire Safety Compliance Certificate' to **M/s. Elite International. School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.** Subject to proper maintenance of firefighting systems In good working condition. And At least 40% of employees should be trained in basic firefighting course at our R.A.Mundkur Fire and Emergency Services Training Academy, Bannerghatta Road, Bangalore-29

This Fire Safety Compliance Certificate is Valid till 09-08-2027 and it is renewable.

Yours faithfully

District Fire Officer
Karnataka Fire & Emergency Service
Tumakuru-572 103

Karnataka Fire and Emergency Services Department

Office of the District fire officer,

Tumkur Fire station

BH Road, Tumkur - 572 103.

Ph No.0816 - 2283101.

No.214/FSR/DFO/TFS/2026.

10-08-2026.

To,
The Authorized Signatory
M/s. Elite International. School,
NS Road, Kadaba,
Gubbi Taluk,
Tumkur District.

Sir

Sub: Issue of Fire safety recommendation to M/s. Elite International School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.

Ref: Your letter dated:09-08-2026.

*****_*****

ANNEXURE-B

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2.
(These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory)

With reference to the subject cited above, I have inspected The premises of M/s. Elite International School, NS Road, Kadaba, Gubbi Taluk, Tumkur District. on 10-08-2026 with respect to Fire prevention, Firefighting and Evacuation measures to be complied in the premises and has submitted the details as under:

A. Details of the building / premises :-


01	Name and Address of the Applicant.	: The Authorized Signatory <u>M/s. Elite International. School,</u> NS Road, Kadaba, Gubbi Taluk, Tumkur District.
02	Name and Address of the premises.	: <u>M/s. Elite International. School,</u> NS Road, Kadaba, Gubbi Taluk, Tumkur District.
03	Name and address of the Building owner	: <u>M/s. Elite International. School,</u> NS Road, Kadaba, Gubbi Taluk, Tumkur District.

(Signature)

04	Number of buildings	:	01 Block.
05	Number of floors:-	:	Ground floor and 02 upper floors.
<u>Floor-wise details of occupancy:-</u>			
06	Ground floor	:	Class rooms-15nos, Library-01no, Office/StaffRoom-01, Sick Room-01, Security Room-01, Store Room-01, Activity Room-01, Sports room-01,
	1 st floor	:	Class rooms-07nos, Computer Lab-01, Math Lab-01, Staff Room-01,
	2 nd Floor	:	Class rooms-10nos, Science Lab-01, Staff Room-01,
07	Height of the buildings:-	:	10.90 Mtrs
08	Site area	:	7438.00 Sq.Mtrs
09.	Built-up area of each floor:-		
	Ground floor	:	1654.83 Sq.Mtrs
	1 st floor	:	775.01 Sq.Mtrs
	2 nd Floor	:	775.01 Sq.Mtrs
10.	Total built-up area	:	3204.85 Sq.Mtrs.
<u>Surrounding properties:-</u>			
11.	West (Front)	:	08.00 Mtrs wide NS Road
	East (Rear)	:	Vacant Land
	North (Side)	:	Areca garden
	South (Side)	:	Vacant Land
<u>Set-back area available around the building :-</u>			
12.	West (Front)	:	01.00 Mtrs
	East (Rear)	:	01.00 Mtrs
	North (Side)	:	113.00Mtrs.
	South (Side)	:	03.00 Mtrs

A. On inspection of this Educational premises, the following fire prevention, firefighting and evacuation measures recommended are considered absolutely essential from fire safety point of view :-

Sl. No. (1)	Details (02)	Existing (03)	Recommendations (04)
01.	Accessibility to the premises	The site is accessible from 08.00 Mtrs wide Road located on Western side. It's hard enough to carry Fire Tender	Complied.
02.	No. of entrances	01 main entrance	Adequate.
03.	Width of entry / exit	01 entry of 3.50 Mtrs width.	Adequate.




04.	Diesel generators.	01 generator of 12.5Kva capacity have been Provided to supply alternate power to all the emergency provision of the buildings.		Complied.
05.	No. of staircases available	Nos. of staircases	: 01 No's.	Adequate
		Width of staircases	: 01.10 Mtrs	
		Width of treads	: 25Cms	
		Height of risers	: 15Cms	
		Nos. of riser per flight	: 14 No's	
		Height of handrails	: 00.90 Mtrs	
		Head room clearance	: 02.90 Mtrs	
06.	No. lifts and capacity.	Nos. of lifts	: NIL	----
		Capacity of lifts	: NIL	
07.	Fire extinguisher	<p>20 Nos ABC fire extinguisher of 06 Kgs capacity Have been Provided.</p> <p>01No Water mist Fire extinguisher of 09Ltrs capacity Have been provided Near the staircase</p> <p>01No Mechanical foam Fire extinguisher of 09 Ltrs capacity Have been provided Near the Generator.</p> <p>01No Co2 Fire extinguisher of 4.5Kg capacity Have been provided Near the Electrical Panel Board.</p>		Complied.
08.	First aid Hose reel hose.	Hose reel hose system of 19 mm dia and having a length of 36.00 Mtrs length Have been installed by tapping them to a vertical pipe of 80 mm internal dia near the landing outlets at ground floor. a pump capable of delivering 450 liters of water per minute.		Complied.
09.	Terrace tank over respective tower terrace.	Overhead tank of 5,000 liters capacity Have been provided.		Complied.
10.	At the terrace tank level with minimum pressure of 3.5 kg/cm ² .	450 ltrs. per minute capacity Booster pump Have been Provided and its connected to the overhead tank.		Complied.

11.	No Smoking Board	COPTA Sec-4 Direction <u>No Smoking area, Smoking here is an offence</u> board should be written in English & Kannada both language have been prominently displayed Building.	Complied.
12.	Escape routes	Escape routes Have been displayed necessary to be fitted because routes are essential for easy exit in the event of a fire.	Complied.
13.	Fire order	Fire safety indicating the details of actions to be taken in case of emergency Have been displayed near each staircase landings with the telephone numbers of our Gubbi Fire Station 08131-222227, and telephone numbers of nearest Ambulance Service.	Complied.
14.	Fire siren	A fire siren Have been installed in the premises to inform the inmates in the case of a fire emergency and evacuate the area.	Complied.
15.	Nominate one fire Nodal officer	The school authority nominated Mr Praveen Kumar as a fire nodal officer.	Complied.
16.	Fire fighting training	04 employees have been trained in basic fire fighting course at our R.A.Mundkur Fire and Emergency Services Training Academy, Bannerghatta Road, Bangalore-29	Complied.

Fire precautionary measures :-

- A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- B. Accumulation of combustible waste in and around the premises should be avoided.
- C. The exit ways shall be always kept clear without any obstruction.
- D. Liquefied petroleum gas should not be stored in the building.




- 5.
- E. The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F. During the class hours the class room doors shall not be locked from inside to outside.
- G. As per Hon'ble supreme court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordinate with fire service department.

Under the above circumstance the Karnataka Fire & Emergency Service Department is issuing 'Fire Safety Recommendation' to M/s. **Elite International. School, NS Road, Kadaba, Gubbi Taluk, Tumkur District.** subject to condition and compliance of the above recommendations in column-4 of serial - B within 3 months and compliance to the undersigned.

This 'Fire Safety Recommendation' is issued for a period of only one year from the date of issue

✦ All requirements recommended above are as per National Building Code- 2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully,

District Fire Officer
Karnataka Fire & Emergency Service.
Tumakuru-572 103

10/08/26